IAINTENANCE SE		upervisor shall in aling materials a		onent/assembly to be repaired to confirm that it cannot be sealed	
outine Maint Supr:	Kavanagh, Steven A.	▼ Phone		Notified On: 12/14/2011 Maint Supr: Kavanagh, Steven A.	
Review/Comments:	Leak source is internal seal ring; cannot be mitigated without leak seal.				
NSPECTION SECT	TON:				
Inspector Name:	Curtis, Scott P.	Phone	2.2488	Notified On: 12/14/2011 Inspector: Curtis, Scott P.	
Thickness:	N/A			☐B Zoom	
Review/Comments:	No issues. No NDE av	ailable.		Hy-Grade Lug Wafer Check Valve is leaking out out of the o-ring where the	OK
NORTH BIO CTO	TOV			flapper/seat insert is installed into the valve body (upstream side). This is not a	UK
	TION: Fixed Equipmen		AND DESCRIPTION OF THE PERSON	of let to be replaced or rebuilt next availible shutdown. Pressure/ temperature of clamps are based on new pipe class 15CS11 (replaces DP1).	Cancel
DPSE: Hill		Phone	2.3200		
			Metallurgy:	CS	
Piping Class: DP:			_		
Piping Class: DP:	•		gn Pressure: 3		
Piping Class: DP: EWO ID: Hy- Design Review: Hy-	-Grade Lug Wafer Check	k Valve is leaking	g out out of the	e o-i	
Piping Class: DP:	-Grade Lug Wafer Check	k Valve is leaking		e o-i	
Piping Class: DP: EWO ID: Hy- Design Review: Hy-	-Grade Lug Wafer Check	k Valve is leaking	g out out of the	e o-i	Eont